DDM INSTALL GUIDE

9006/9005/H10 HID Low Beam Kit (35W or 55W)



TOOLS NEEDED: Simple hand tools, depending on if you need to remove lights. **READ FIRST:** This install guide will work with 9006, 9005, H10 bulb types. Usually removal of the headlight isn't necessary. However for the purpose of this install guide we chose to remove the headlight assembly. Note: We are using a 2007 Chevy Silverado for our install. Depending on vehicle, removal of your headlight may differ.

DIFFICULTY: Easy




Open hood. Look down from above into the engine bay and locate the low beam bulb. Remove retaining clip on the low beam by simultaneously unclipping and pulling the connector away from the bulb.

Professional Install



Removal of headlight housing (if required).

Please refer to your car's owners manual for instruction on headlight removal.



Twist OEM bulb counter clockwise to unlock the bulb from headlight housing. Once the bulb is unlocked remove gently from housing.

3





Adapter harnesses are not necessary for this HID installation. If desired you can cut and remove the adapter harnesses as pictured to left.

DDM Tip: Be very careful **NOT** to cut the HID bulb wires (bulb wires are picture to left WITH RED ARROWS). Your bulb warranty will be void if you cut the HID bulb wires.



Insert the male connector (the connector that came out of your OEM bulb) into the female connector coming out of the ballast. Mount ballast with the double sided tape provided to a clean flat surface in the engine bay.



Remove the HID bulb from the protective plastic casing and screw cap. Do not touch the bulb with your bare hands. If you do, be sure to clean the bulb with rubbing alcohol prior to installation.

-



Connect corresponding AMP connectors from the ballast to bulb.



Twist bulb clockwise into place locking it securely into the headlight housing.



Slide the rubber grommet up to the bulb plug which keeps the bulb protected from the elements.

DDM Tip: At this stage of the install we recommend turning on lights to make sure everything works before proceeding.



Reinstall headlight assembly if removal was required.